

# Thermac Pty. Ltd.

2 Panoramic Terrace,  
BERWICK, VICTORIA, 3806  
AUSTRALIA.

Tel: 61 3 9707 4215

Email: [thermac@bigpond.com.au](mailto:thermac@bigpond.com.au)

ABN 69 007 449 256

23/10/17

## Re: Service Life of the Thermac Model 1000 heat detector.

Service Life: 10 years of continuous service then replacement.

Warranty Period: 2 years from date of sale.

### Note:

While a ten year service life is recommended, conditions in the field can vary greatly.

If conditions are severe then it is recommended that periodic detector **sensitivity testing** (2 years) will determine their continued serviceability over the maximum 10 year life.

If conditions are benign then it is recommended that periodic detector **sensitivity testing** (5 years) will determine their continued serviceability over the maximum 10 year life.

On site **function checks** to AS1851 Section 6 App G are required **annually**.